

03500.015667.



Cof

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

) : Examiner: C. Hannaher

KENJI KAJIWARA ET AL.

; Group Art Unit: 2878

Appln. No.: 09/922,641

)

Filed: August 7, 2001

)

For: **LARGE-AREA FIBER PLATE,
RADIATION IMAGE PICKUP
APPARATUS UTILIZING THE
SAME AND PRODUCING
METHOD THEREFOR**

) Certificate
:
)
:
)
of Correction

U.S. Patent No.: US 6,800,857 B2

)

Issued: October 5, 2004

) November 30, 2004

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

12/02/2004 ZJUHAR2 00000039 6800857

100-00 DP


01 FC:1811

DEC 07 2004

Accompanying this letter is a check for \$100.00 to cover the statutory fee
for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by
telephone at (212) 218-2100. All correspondence should continue to be directed to our
address given below.

Respectfully submitted,



John A. Krause
Attorney for Patentees
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 467132v1

DEC 07 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only

PRINTER'S TRIM LINE

PATENT NO. : US 6,800,857 B2

DATED : October 5, 2004

INVENTOR(S) : KENJI KAJIWARA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 32, "No. 5,563,414," should read --No. 5,563,414),--.

COLUMN 3:

Line 16, "are" should read --is--.

COLUMN 4:

Line 2, "are" should read --is--.

COLUMN 5:

Line 25, "poslished" should read --polished--; and
Line 54, "poslished" should read --polished--.

COLUMN 9:

Line 23, "a" should be deleted.

COLUMN 10:

Line 53, "picth" should read --pitch--; and
Line 63, "and e" should read --and θ--.

COLUMN 11:

Line 22, "coefficient" should read --coefficient,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,857 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,800,857 B2

DATED : October 5, 2004

INVENTOR(S) : KENJI KAJIWARA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 29, "refleccted" should read --reflected--.

COLUMN 13:

Line 59, "aluminum" should read --aluminum,--; and

Line 62, "compounds" should read --compounds,--.

COLUMN 14:

Line 54, "Cd etc." should read --Cd, etc.,--.

COLUMN 15:

Line 66, "is" should read --are--.

COLUMN 18:

Line 7, "and intercepted" should read --and is intercepted--; and

Line 29, "in inclined" should read --in an inclined--.

COLUMN 20:

Line 5, "are" should read --is--.

COLUMN 22:

Line 18, "between" should read --between--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,857 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only

PRINTER'S TRIM LINE

PATENT NO. : US 6,800,857 B2

DATED : October 5, 2004

INVENTOR(S) : KENJI KAJIWARA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 12, "element" should read --elements--; and
Line 43, "element" should read --elements--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,857 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,800,857 B2

DATED : October 5, 2004

INVENTOR(S) : KENJI KAJIWARA ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 32, "No. 5,563,414," should read --No. 5,563,414),--.

COLUMN 3:

Line 16, "are" should read --is--.

COLUMN 4:

Line 2, "are" should read --is--.

COLUMN 5:

Line 25, "poslished" should read --polished--; and
Line 54, "poslished" should read --polished--.

COLUMN 9:

Line 23, "a" should be deleted.

COLUMN 10:

Line 53, "picth" should read --pitch--; and
Line 63, "and e" should read --and θ--.

COLUMN 11:

Line 22, "coefficient" should read --coefficient,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,857 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,800,857 B2

DATED : October 5, 2004

INVENTOR(S) : KENJI KAJIWARA ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 29, "refleccted" should read --reflected--.

COLUMN 13:

Line 59, "aluminum" should read --aluminum,--; and

Line 62, "compounds" should read --compounds,--.

COLUMN 14:

Line 54, "Cd etc." should read --Cd, etc.,--.

COLUMN 15:

Line 66, "is" should read --are--.

COLUMN 18:

Line 7, "and intercepted" should read --and is intercepted--; and

Line 29, "in inclined" should read --in an inclined--.

COLUMN 20:

Line 5, "are" should read --is--.

COLUMN 22:

Line 18, "betgween" should read --between--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,857 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,800,857 B2

DATED : October 5, 2004

INVENTOR(S) : KENJI KAJIWARA ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 12, "element" should read --elements--; and
Line 43, "element" should read --elements--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,800,857 B2

No. of add'l. copies
@ 30¢ per page